



COMPUTER INTEGRATED MANUFACTURING LAB MANUAL (17MEL77)



DEPARTMENT OF MECHANICAL ENGINEERING
BAPUJI INSTITUTE OF ENGINEERING AND TECHNOLOGY

DAVANGERE-577 004



DEPARTMENT OF
MECHANICAL ENGINEERING

COMPUTER INTEGRATED
MANUFACTURING LAB MANUAL
2018
(17MEL77)

As per VTU Syllabus CBCS scheme for VII Semester

Name :

USN :

Semester:..... Batch No

Ravikumar H.N

Faculty Incharge

Mallikarjuna V.K

Instructor



BAPUJI INSTITUTE OF ENGINEERING AND TECHNOLOGY

DAVANGERE- 577 004

VISION OF THE INSTITUTE

To be center of excellence recognized nationally and internationally, in distinctive areas of engineering education and research, based on a culture of innovation and invention.

MISSION OF THE INSTITUTE

BIET contributes to the growth and development of its students by imparting a broad based engineering education and empowering them to be successful in their chosen field by inculcating in them positive approach, leadership qualities and ethical values.

VISION OF THE DEPARTMENT

The department endeavors to be a center of excellence, to provide quality education leading the students to become professional mechanical engineers with ethics, contributing to the society through research, innovation, entrepreneurial and leadership qualities.

MISSION OF THE DEPARTMENT

1. To impart quality technical education through effective teaching- learning process leading to development of professional skills and attitude to excel in Mechanical Engineering.
2. To interact with institutes of repute, to enhance academic and research activities.
3. To inculcate creative thinking abilities among students and develop entrepreneurial skills.
4. To imbibe ethical, environmental friendly and moral values amongst students through broad based education

PROGRAM EDUCATIONAL OBJECTIVES (PEO'S)

1. Enable to understand mechanical engineering systems those are technically viable, economically feasible and socially acceptable to enhance quality of life.
2. Apply modern tools and techniques to solve problems in mechanical and allied engineering streams.
3. Communicate effectively using innovative tools, to demonstrate leadership and entrepreneurial skills.
4. Be a professional having ethical attitude with multidisciplinary approach to achieve self and organizational goals.
5. Utilize the best academic environment to create opportunity to cultivate lifelong learning skills needed to succeed in profession.

PROGRAM SPECIFIC OUTCOMES (PSO'S)

PS01:-Apply the acquired knowledge in design, thermal, manufacturing and interdisciplinary areas for solving industry and socially relevant problems.

PS02:-To enhance the abilities of students by imparting knowledge in emerging technologies to make them confident mechanical engineers.

COMPUTER INTEGRATED MANUFACTURING LAB B.E, VII Semester, Mechanical Engineering [As per Choice Based Credit System (CBCS) scheme]			
Course Code	17MEL77	CIE Marks	40
Number of Lecture Hours/Week	03 (1 Hour Instruction+ 2 Hours Laboratory)	SEE Marks	60
Total Hours	40	Exam Hours	03
Credits –02			

Course Objectives:

CLO1	To expose the students to the techniques of CNC programming and cutting tool path generation through CNC simulation software by using G-Codes and M-codes
CLO2	To educate the students on the usage of CAM packages and cut part on virtual CNC machine simulator.
CLO3	To make the students understand the importance of automation in industries through exposure to FMS, Robotics, and Hydraulics and Pneumatics.

Part-A

Manual CNC part programming for 2 turning and 2 milling parts. Selection and assignment of tools, correction of syntax and logical errors, and verification of tool path.

CNC part programming using CAM packages. Simulation of Turning, Drilling, Milling operations. 3 typical simulations to be carried out using simulation packages like: Cadem CAM Lab-Pro, Master- CAM.

Program generation using software. Optimize spindle power, torque utilization, and cycle time. Generation and printing of shop documents like process and cycle time sheets, tool list, and tool layouts. Enter program, take tool offsets, cut part in single block and auto mode, measure the virtual part on screen in the virtual CNC machine simulator, for standard CNC control systems FANUC, FAGOR, HAAS and SINUMERIK.

Part B

(Only for Demo/Viva voce)

FMS (Flexible Manufacturing System): Programming of Automatic storage and Retrieval system (ASRS) and linear shuttle conveyor Interfacing CNC lathe, milling with loading unloading arm and ASRS to be carried out on simple components.

(Only for Demo/Viva voce)

Robot programming: Using Teach Pendant & Offline programming to perform pick and place, stacking of objects (2 programs).

Pneumatics and Hydraulics, Electro-Pneumatics: 3 typical experiments on Basics of these topics to be conducted.

After studying this course, students will be able to:

Course Outcomes:

CO1	Understand & write CNC part program for Turning, Facing, Chamfering, Grooving, Step turning, Taper turning, Circular interpolation etc.
CO2	Analyse CNC Mill Part programming for Point to point motions, Line motions, Circular interpolation, Contour motion, Pocket milling- circular, rectangular, Mirror commands etc.
CO3	choose high end CAM packages for machining complex parts and state of art cutting tools and related cutting parameters; optimize cycle time, set up and cut part on and use Canned Cycles for Drilling, Peck drilling, Boring, Tapping, Turning, Facing, Taper turning Thread cutting etc.
CO4	Simulate Tool Path for different Machining operations of small components using CNC Lathe & CNC Milling Machine. Understand & write programs for Robot control; understand the operating principles of hydraulics, pneumatics and electro pneumatic systems.

Scheme for Examination:

Two Questions from Part A - 60 Marks (30 +30) Viva-Voce - 20 Marks

Total: 80 Marks

DO's

1. Students must always wear uniform and shoes before entering the lab.
2. Proper code of conduct and ethics must be followed in the lab.
3. Windows and doors to be kept open for proper ventilation and air circulation.
4. Check for the electrical connections and inform if any discrepancy found to the attention of lecturer/lab instructor.
5. Perform the experiment under the supervision/guidance of a lecturer/lab instructor only.
6. In case of fire use fire extinguisher/throw the sand provided in the lab.
7. Any unsafe conditions prevailing in the lab can be brought to the notice of the lab in charge.

DONT's


1. Do not touch any system without their prior knowledge,
2. Never overcrowd the laboratory Leave sufficient space for the person to operate the equipment's.
3. Never rest your hands on the system and the display board.

CONTENTS

SL.	TITLE	PAGE NO
	PART-A	
1	CNC PART PROGRAMMING	1-1
	GENERALLY USED G-CODES IN TURNING	2-2
	GENERALLY USED G-CODES IN TURNING	3-3
	LIST OF G & M CODES USED IN SSCNC FOR TURNING CENTER	4-4
2	GENERATE ABSOLUTE PART PROGRAM TO CREATE THE FOLLOWING PROFILE WITH FACING AND OD TURNING AND WRITE COMMENTS.	5-15
3	WRITE A PART PROGRAM TO CREATE THE FOLLOWING PROFILE WITH FACING AND OD TURNING. ABSOLUTE, INCREMENTAL AND INCREMENTAL WITH USING CANNED CYCLE AND WRITE THE COMMENTS OF THE EACH LINE PROGRAM.	16-17
4	WRITE A PART PROGRAM TO CREATE THE FOLLOWING PROFILE WITH FACING, OD TURNING AND STEP TURNING WRITE THE COMMENTS OF THE EACH LINE PROGRAM.	18-19
5	WRITE A PART PROGRAM TO CREATE THE FOLLOWING PROFILE WITH STEP TURNING (UNDER CUT) WRITE THE COMMENTS OF THE EACH LINE PROGRAM.	20-20
6	WRITE A PART PROGRAM TO CREATE THE FOLLOWING FACING OD TURNING AND TAPER PROFILE USING G90 AND G94 FIXED CYCLE WITH FACING, TAPER TURNING WRITE THE COMMENTS OF THE EACH LINE PROGRAM.	21-22
7	WRITE A PART PROGRAM TO CREATE THE FOLLOWING UNDER STEP CUTTING AND THREAD CUTTING PROFILE USING G90 AND G92 FIXED CYCLE WRITE THE COMMENTS OF THE EACH LINE PROGRAM.	23-24
8	WRITE A PART PROGRAM TO CREATE THE FOLLOWING UNDER STEP CUTTING AND CONCAVE, CONVEX CUTTING PROFILE USING G90 AND G02 CIRCULAR CYCLE WRITE THE COMMENTS OF THE EACH LINE PROGRAM.	25-26

9	WRITE A PART PROGRAM TO CREATE THE FOLLOWING UNDER STEP CUTTING AND CONCAVE, CONVEX CUTTING, USING G90 AND G02 AND G03 CIRCULAR CYCLE WRITE THE COMMENTS OF THE EACH LINE PROGRAM.	27-29
10	WRITE A PART PROGRAM TO CREATE THE FOLLOWING PECK DRILLING OPERATION USING G74 AND Q PECK DISTANCE IN MICRONS.	30-31
11	USING SWANSOFT WRITE A PART PROGRAM TO CREATE THE FOLLOWING PROFILE WITH FACING, TURNING, STEP TURNING, DRILLING, CONCAVE/CONVEX AND THREAD CUTTING M50 X 3MM PITCH, CHOOSE A WORK PIECE OF SIZE 55 DIAMETER 250 LENGTHS.	32-32
PART-B		
OPERATING PROCEDURE OF MASTER CAM		
12	TO PREPARE THE EXERCISE 1 MODEL AS PER THE SKETCH USING MASTER CAM TOOL.	33-48
13	TO PREPARE THE EXERCISE 1 MODEL AS PER THE SKETCH USING MASTER CAM TOOL.	49-57
14	TO PREPARE THE EXERCISE 1 MODEL AS PER THE SKETCH USING MASTER CAM TOOL.	58-75

CIM LAB LAY OUT



CNC PART PROGRAMMING

Software: SwanSoft FANUC 0iT CNC Turning

List of G & M Codes used in SSCNC for Turning Center

GENERALLY USED G-CODES IN TURNING

STANDARD G CODE FUNCTION

G00	Positioning in Rapid
G01	Straight Interpolation
G02	Circular Interpolation (CW)
G03	Circular Interpolation (CCW)
G04	Dwell
G10	Change in Setting Value
G20	Data Input in Inch
G21	Data Input in metric
G22	Stored Stroke Limit on
G23	Stored Stroke Limit off
G25	Spindle Speed Fluctuation detection OFF
G26	Spindle Speed Fluctuation detection ON
G27	Machine Reference Check
G28	Automatic Machine Reference
G29	Return From Reference
G30	The 2nd Reference return
G31	Skip Function
G32	Threading Process Cycle
G40	Cancel of Compensation
G41	Compensation of the left
G42	Compensation of the right
G65	Call custom Macro
G70	Repeat Cycle - Finishing
G71	Stock Removal in Turning
G72	Stock Removal in Facing
G73	Pattern Repeating Cycle
G74	Peck Drilling in Z Direction
G75	Grooving in X - Direction
G76	Thread Process Cycle
G90	Fixed Process Cycle in Turning
G92	Fixed Process Cycle in Threading
G94	Fixed Process Cycle in Facing
G96	Constant Surface speed
G97	Constant Surface speed cancel
G98	Per min feed
G99	Per revolution feed


GENERALLY USED M-CODES IN TURNING

STANDARD M CODES	FUNCTION
M00	Unconditional program stop
M01	Conditional program stop
M02	End of Program with return to program start
M03	Spindle Rotation, Clock Wise
M04	Spindle Rotation, Counter Clock Wise
M05	Spindle Stop
M06	Tool Change
M08	Coolant ON
M09	Coolant OFF
M30	End of Program, Reset and return to program beginning
M94	Cancel Mirror Image
M95	X Coordinate Mirror Image
M96	Y Coordinate Mirror Image
M98	Subprogram call
M99	End of Sub Program

List of G & M Codes used in SSCNC for Turning Center

Function	Address	Meaning of address
Program number	O(EIA)/(ISO)	Program number
Block sequence number	N	Sequence number
Preparatory function	G	Specifies a motion mode (Linear, arc, etc)
Dimension word	X, Z	Command of moving position(absolute type) of each axis
	U, W	Instruction of moving distance and direction(incremental type)
	I, K	Ingredient of each axis and chamfering volume of circular center
	R	Radius of circle, corner R, edge R
Feed function	F, E	Designation of feedrate and thread lead
Auxiliary function	M	Command of ON/OFF for operating parts of machine
Spindle speed function	S	Designation of speed of main spindle or rotation time of main spindle
Function (Tool)	T	Designation of tool number and tool compensation number
Dwell	P, U, X	Designation of dwell time
Designation of program number	P	Designation of calling number of auxiliary program
Designation of sequence No	P, Q	Calling of compound repeat cycle, end number
Number of repetitions	L	Repeat time of auxiliary program
Parameters	A, D, I, K	Parameter at fixed cycle

1. Write a Absolute part program to create the following profile with facing and OD Turning and write comments.



Work piece Information

Bar

Diameter: 70.000

Length: 250.000

Material:08F low-carbon steel

Tool Information

- Work offset at the center
- Tools Management – Select the External turning 35° / 90° tool.

Procedure

Choose the stand alone button

Click on drop down button

Select Fancu OiT CNC System

Select MAC Encryption


Go to Run

Release the Emergency button






Press write protect off




Press Reference and X and Z

Go to Parameter setting




Press parameter setting button to open Parameter setting window.

Select– 4 Position turret and press ok



Workpiece Setting, Go to – Stock size





Choose Length of Work Piece =250mm

- Choose Diameter of the Work Piece=80mm
- Check Replace work piece button to replace existing work piece .
- Press OK button.

Tool Management:

- Add New Tool
- Edit Tool

- Tool Selection



Enter Diameter and Length of the tool in respected places


- Enter Rpm and Feed .
- Enter thickness of the insert.
- Enter Shank and its width.
- Then click OK button to add the toll to Library.

– select the External turning 35/55/90⁰ tool – drag and drop to tool magazine– mount the tool

Workpiece setting – rapid position at center



Press Work set setting Button to view above Menu. To open **Locate instantly window** select Rapid Position button.




Select the position and press OK button.

Close the machine door


Offset setting – work – X00 – measure --- Z00 – measure

(Do not use this step if X and Z axis home position is zero)



Getting Ready to enter your first program

Before writing program you have to register for memory space.



prog – edit – DIR – O0013 (Register your program No. start with alphabet ‘O’)

Press **DIR** Button in the Numerical panel to register the program. Type registry number in **Program panel**.

The registry number start with letter ‘O’


Followed by number (ex: **O0009**).



Type the program by using Program panel or by using the computer key board .



In program panel press letter in smaller font press **Shift** then press button for example to type letter p press **Shift** then press **O and P** Button. After entering one line of code press **EOB** button press **Insert** button add this code to numerical control panel.




Absolute Method	Comments / Remarks
O0012	Program Number
G54	Work co-ordinate system
T0100	Tool T01 selection
S400M03	Spindle to rotate at 400 RPM in Clockwise direction
M08	Coolant on
G00X00Z00t0101F2.5	Tool T01 Positions in Rapid traverse
G00X71	1 mm away from the set coordinate
G01X0Z-1F0.25	Lanier Interpolation (G01) Movements in X & Z Directions to create the paths. The feed is at 0.25mm/rev. Table feed = 0.25 x 400 rpm = 45mm/min
G00X71	
G01Z-5	
G01X0	
G00X71Z-5	
G01X65	
G01Z-205	
G00X66Z-5	
G01X60	
G01Z-205	
G00X61	
G28U0W0	Go Back to tool change position in rapid (m/c 00)
M09	Coolant off
M05	Spindle off
M30	Program End

After entering the program

Go to Auto mode

Select block by block

Cycle Start




Auto mode

Block

Cycle Start

2. Write a part program to create the following profile with facing and OD Turning. Absolute, Incremental and Incremental with using canned cycle and write the comments of the each line program .



Work piece Information

Bar
Diameter: 80.000
Length: 250.000
Material:08F low-carbon steel

Tool Information


- Work offset at the center
- Tools Management – Select the External turning $35^{\circ} / 90^{\circ}$ tool.

Procedure


1. Release the Emergency button
2. Press Reference and X and Z
3. Press write protect off
4. Go to Parameter setting – 4 Position turret
5. Tools Management – select the External turning $35/55/90^{\circ}$ tool – drag and drop to tool magazine– mount the tool
6. Workpiece setting – stock size – $\varnothing 80$, 250 length
7. Workpiece setting – rapid position at center
8. Close the machine door
9. Offset setting – work – X00 – measure --- Z00 – measure
(Do not use this step if X and Z axis home position is zero)
10. prog – edit – DIR – O0013 (Register your program No. start with alphabet ‘O’)

CNC Codes

Absolute Method	Incremental	Incremental with using canned cycle
O0012 G54 T0100 S400M03M08 G00X00Z00F2.5 G00X81 G01X0Z-1F0.25 G00X81 G01Z-5 G01X0 G00X81Z-5 G01X77.5 G01Z-205 G00X78.5Z-5 G01X75 G01Z-205 G00X76 G28U0W0 M09 M05 M30	O0012 G54 T0100 S400M03M08 G00X00Z00F2.5T0101 G00U81 G01W-2.5F0.25 G01U-81 G00U81 G01W-5 G01U-81 G00U81 G00W5 G01U-3.5 G01W-200 G00U1W205 G01U-3.5 G01W-205 G00U1 G28U0W0 M09 M05 M30	O0012 G54 T0100 S400M03M08 G00X00Z00F2.5T0101 G00U81 G94U-81W-2F0.25 W-4 W-5 G90U-3W-200F0.25 U-4 U-5 G28U0W0 M09 M05 M30



3. Write a part program to create the following profile with facing, OD Turning and Step Turning write the comments of the each line program .



Workpiece Information


Bar
 Diameter: 80.000
 Length: 250.000
 Material:08F low-carbon steel

Tool Information


- Work offset at the center
- Tools Management – Select the External turning 35° tool.

CNC Codes

Absolute Method	Incremental	Incremental with using canned cycle
O0017	O0017	O0017
G54	G54	G54
T0100	T0100	T0100
S500M03M08T0101	S500M03M08T0101	S500M03M08T0101
G00X00Z00F0.25	G00X00Z00F0.25	G00X00Z00F0.25
G00X50	G00U50	G00U80
G01X50Z-50F0.26	G01W-50F0.26	G90U-2W-150F0.25
G01X60	U10	U-4
G01Z-100	W-50	U-6
G01X70	U10	U-8
G01Z-160	W-50	U-10
G01X80	U10	G90U-12W-100F0.25
G28U0W0	G28U0W0	U-14
M09	M09	U-16
M05	M05	U-18
M30	M30	U-20
		G90U-22W-50F0.25
		U-24
		U-26
		U-28
		U-30
		G28U0W0
		M09
		M05
		M30



4. Write a part program to create the following profile with Step Turning (under cut)
write the comments of the each line program .



Workpiece Information


Bar
Diameter: 80.000
Length: 200.000
Material:08F low-carbon steel

Tool Information


- Work offset at the center
- Tools Management – Select the Grooving tool with thickness of 1mm and that edge also taken into consideration. (move 1mm and give 19mm cutting)

CNC Code

```
O0022
G56T0200S400M03M08
G00X00Z00F0.25
U81
W-100
W-1
G90U-2.5W-19F0.25
U-5
U-7.5
U-10
U-12.5
U-15
U-17.5
U-20
M09M05M30
%
```



5. Write a part program to create the following Facing OD Turning and Taper profile using G90 and G94 fixed cycle with facing, Taper Turning write the comments of the each line program ..



Work piece Information: Bar

Diameter: 80.000

Length: 250.000


Material:08F low-carbon steel

Tool Information


- Work offset at the center
- Tools Management – select the External turning 35° tool – drag and drop tool.

CNC Codes

Absolute Method	Incremental
O0017	O0017
G54	G54
T0100	T0100
S500M03M08T0101	S500M03M08T0101
G00X00Z00F0.25	G00X00Z00F0.25
G00X80	G00U80
G94X0Z-2F0.25	G94U-80W-2F0.25
Z-4	W-4
Z-5	W-5
G90X78Z-155F0.25	G90U-2W-155F0.25
X76	U-4
X75	U-5
Z-35R-2.5	W-35R-2.5
Z-65R-5	W-65R-5
Z-95R-7.5	W-95R-7.5
Z-125R-10	W-125R-10
Z-155R-12.5	W-155R-12.5
G28U0W0	G28U0W0
M09	M09
M05	M05
M30	M30



5. Write a part program to create the following Under Step Cutting and Thread Cutting profile using G90 and G92 fixed cycle write the comments of the each line program .



Work piece Information:

Bar
 Diameter: 80.000
 Length: 200.000
 Material:08F low-carbon steel

Tool Information

- Work offset at the center
- Tools Management –
 First Select the Grooving tool with thickness of 1mm and that edge also taken into consideration. (move 1mm and give 19mm cutting)


Second select the Thread cutting tool Insert parameter Length 2.5 insert thickness and insert diameter 12 tool – drag and drop tool.

$$\text{Pitch} = 0.061 \times \text{diameter}$$


CNC Code

```
O0022
G54T0100S400M03M08
G00X00Z00F0.25
U81
W-100
W-1
G90U-2.5W-19F0.25
U-5
U-7.5
U-10
U-12.5
U-15
U-17.5
U-20
G00U2
```

G28U0W0
G55
T0200S400M03M08
G00X0Z0F0.25
G00U81W1
G92U-1W-105F0.25
U-3
U-5
G28U0W0
M09M05M30
%



6. Write a part program to create the following Under Step Cutting and Concave, Convex Cutting profile using G90 and G02 circular cycle write the comments of the each line program ..



Work piece Information

Bar
 Diameter: 80.000
 Length: 200.000
 Material:08F low-carbon steel


Tool Information

- Work offset at the center
- Tools Management – First Select the Grooving tool with thickness of 1mm and that edge also taken into consideration. (move 1mm and give 19mm cutting)


CNC Code

```
O0023
G54
T0100M03M08S400
G00X0Z0F025
G00U81
W-21
G90U-5W-19F0.25
U-10
U-15
U-20
G00W-40
G90U-5W-19F0.25
U-10
U-15
U-20
```

G00
U2
W60
U-2
G02U-10W-10R10
G02U10W-9R10
G00
W-20
U-11
G03U10W-10R10
G03U-10W-11R10
G00W-1U11
G28U0W0
M09M05M30
%



7. Write a part program to create the following Under Step Cutting and Concave ,Convex Cutting, using G90 and G02 and G03 circular cycle write the comments of the each line program .



Work piece Information

Bar

Diameter: 80.000

Length: 200.000

Material:08F low-carbon steel

Tool Information


- Work offset at the center
- Tools Management

Select the Grooving tool with thickness of 1mm.for step turning and single point cutting tool 35° angle length 15mm, insert thickness 3mm for convex and concave


CNC Code

```
O0024
G54
T0100M03M08
X0Z0
G00U81
W-21
G90U-5W-19F0,25
U-10
U-15
U-20
```

G00W-40
G90U-5W-19F0.25
U-10
U-15
U-20
G00W-40
G90U-5W-19F0.25
U-10
U-15
U-20
G28U0W0
G55
T0200
G00X0Z-10
G02U-10W10R10
G00U11
W-15
U-1
G02U-15W15R15
G00U16
W-20
U-1
G02U-20W20R20
G00U21
W-40
U-1
G02U-10W-10R10
G02U10W-10R10
G00U1
W-20U-11
G03U10W-10R10
G03U-10W-10R10
G00W-1
U11
G28U0W0
M05M09M30
%



8. Write a part program to create the following peck drilling operation.
using G74 and Q peck distance in microns.



Work piece Information


Bar
Diameter: 75
Length: 200
Material: 08F low-carbon steel

Tool Information


- Work offset at the center
- Tools Management – Select the drilling tool with diameter 10mm. Q is pecking distance in microns.

CNC Code

```
O0024  
G54  
T0100M03M08  
X0Z0  
G74R5  
G74W-40Q10000F0.5  
G28U0W0  
M09M05M30  
%
```





- Q is pecking distance in microns.



Exercise :

9. Using Swansoft write a part program to create the following profile with Facing, Turning, Step Turning, Drilling, Concave/Convex and Thread Cutting M50 x 3mm pitch, choose a work piece of size 55 diameter 250 length.



OPERATING PROCEDURE OF MASTER CAM

Step 1

The usual modification is that is done after initializing the master cam is the alteration of the available screen ie modification of grid size and as per the requirement of user screen, configure, selection grid. Select grid size (configure

→ grid) The dimensioning requirement is usually selected ie Metric or English etc.

Step 2

Once the screen and the dimensioning adjustments are done the basic required part geometry of the object is created by using the create command.

Create command: Rectangle or Circle or Line or Fillet.

Step 3

After defining the tool parameters and the machining operations parameter, the job setup is done. The job is usually defined in terms of length width and thickness (X, Y, Z). The selection of material for the job is done in jobsetup

Step 4

After the required part geometry is created, the tool path are defined on the selected geometry depending upon the milling operation.

Tool path → contour → save → chain → done

Tool path → pocket → save → area or chain or polygon → done

Once the tool path are defined, press done, tool parameter screen will appear where in the required tool diameter is entered or the tool can be selected from the tool manager.

Similarly the above step is carried out for all operations the contour parameter such as clearance, retract, feed, top of stock, depth are given.

Step 5


Completion of the above setup leads to operation manager where in all the operation are selected by select all, paths are regenerated by Regenerate path, and by Verify, machining operation is done. Before machining, configuration is verified where in use of job setup values are highlighted.

Step 6

Press post button to the get the NC program

Exercise 1

Aim : To machine the model as per the sketch.



Procedure:

Step 1

The usual modification is that is done after initializing the master cam is the alteration of the available screen ie modification of grid size and as per the requirement of user screen,


Choose-mainmenu → Screen → Configure → Current Configuration File

Select- Mill9.Mcfg(metric)

Choose-mainmenu → Screen → Nextmenu → Sel.Grid

Select-Active Grid, Visible Grid, Spacing x =1 and y =1, Grid Size= 110,

Origin x=0,y=0 and choose suitable for Grid.



Step 2

1. To create inner and outercircles.


- Choose-mainmenu → Create → Arc → circpt+dia.
- Typediameter100 → Enter
- Selectorigin
- Press Esc. And reselectcircpt+dia
- Enter diameter58
- Selectorigin
- Press Esc. And reselectcircpt+dia
- Repeat same procedure for diameter 20 and22mm
- xi. Press Esc. to exit circle function
- Choose it screenmenu.

2. To create construction of rectangle /Square

- Choose-mainmenu → Create → Rectangle → 1 point
- Enter width 92 and height 92 (bcz. given figure is square) pressOK
- Selectorigin
- Press Esc to exit linefunction

3. Trimming unwanted portion oflines

- Choose-mainmenu → Modify → Trim → 3 entities
- Select 1 entity as vertical line of square inside the circle
2 entity as Horizontal line of square inside the circle
3 entity as arc of the circle inside the square.



4. Copy and rotate the arc

- Choose-mainmenu → Xform → Rotate
- Select anywhere on arc.
- Choosedone.
- Selectorigin.
- Select copy, enter the values. No of steps 3 and angle is 90°
- Choose OK in the dialogue box remaining slots for created.

XFORM	ANALYSE	DELETE	FILE
MIRROR	POINT	CHAIN	NEW
ROTATE	CONTOUR	WINDOW	EDIT
SCALE	ONLY	POLYGON	GET
ACALEXYZ	BETWEEN PTS	AREA	MERG
TRANSLATE	ANGLE	ONLY	E LIST
OFFSET	DYNAMIC	ALL	SAVE
GS COLOUR	AREA/VOLUM	GROUP	SAVE SOME
GROUP	E NUMBER	RESUIT	BROWSE
STRETCH	CHAIN	DUPLICATE	CONVERT
ROLL	SURFACE	UNDELETE	ER NEXT
BACK UP	BACKUP	BACKUP	MENU

5. Trimming unwanted portion of lines(Square)

- Choose-mainmenu → Modify → Trim → 3entities
- Select
 - 1 Entity vertical line of square inside the arc
 - 2 Entity Horizontal line of square inside the arc
 - 3 Entity arc inside the square.

6. To create construction lines

- Choose-mainmenu → Create → Line → Polar
- Enter the first co-ordinate origin
- Enter angle in degree 45^0
- Enter the line length 45
- Press Esc to exit line function

7. To create inner 10 mm diameter circles

- Choose- mainmenu → Create → Arc → circpt +dia.
- Type diameter 10 → Enter
 - Select end point of inclined line.
- Press Esc. And reselect circpt+dia

8. Copy and rotate the Circle

- Choose-mainmenu → Xform → Rotate
- Select anywhere on 10 mm diameter circle
- Chooedone.
- Selectorigin.
- Select copy, enter the values. No of steps 3 and angle is 90^0
- Choose OK in the dialogue box remaining 3 circles for created.

Now your drawing is ready for operations

The following operations to be conduct Using the geometry

- **Facing**
- **Contour**
- **Pocketing**
- **Drilling**


Step 3

1. Make job setup for givengeometry

- Choose-mainmenu → Toolpath → Job setup
- Enter the X =110 Y=110 and Z=55 mmrespectively
- Select Display Stack and Fit toScreen.
- Outside the drawing dotted boundary red line isdisplayed

2. Another option for jobsetup



- Choose-mainmenu → Toolpath → Jobsetup
- Select stock origin (0,0)
- select the stockcorners.
- Enter the value of Z = 55 (+ value).
- Select the display stock checkbox.
- Select fit stock checkbox.
- Choose OK the stock should be enclosed by red dottedline.



Step 4


1. Create tool path for Facing

- Choose-mainmenu → Toolpath → Face
- Select start point for the chain at periphery of the figure.
- Choosedone.
- Right click in the tool display area and select a 10 mm flat endmill
- from the toollibrary.
- Right click on the tool display , go to tool type select face mill tool,
- Select the facing parameters. Give Depth of cut -2mm (-negative)
- Select depth Cuts, Give Rough Cut 3, Finishing cut 1No. Finish Step0.5
- Choose OK twice in the tool path should be showing figure.



1. Create tool path for Contour

- Choose-mainmenu → Toolpath → Contour
- Select start point for the chain at position 1.
- Choosedone.
- Right click in the tool display area and select a 10 mm flat end mill from the toollibrary.
- Select the contour parameters , Give Depth of cut -53mm (- negative), Use Multi passes, Depth Cuts and Lead in/outoptions.
- Choose OK twice in the tool path should be showingfigure.



3. Create tool path for pocket 1

- Choose-mainmenu → Toolpath → Pocket
- Select the 58 mm diameter circle.
- Choosedone.
- Right click in tool display area and select 8mm flat end mill from toollibrary.
- Enter pocketing parameters and note that the depth shouldbe negative say-10.
- Choose OK the tool path should look like the picturepattern.

4 Create tool path for pocket 2

- Choose-mainmenu → Toolpath → Pocket
- Select first 22 mm diameter circle.
- Choose done.
- Right click in tool display area and select 5mm flat end mill from tool library.
- Enter pocketing parameters and note that the depth should be negative -12.
- Choose OK the tool path should look like the picture pattern.

6. Create tool path for pocket 3

- Choose-mainmenu → Toolpath → Pocket
- Select first 20 mm diameter circle.
- Choose done.
- Right click in tool display area and select 3mm flat end mill from tool library.
- Enter pocketing parameters and note that the depth should be negative say -32.
- Choose OK the tool path should look like the picture pattern.


6. Create tool path for Drilling

- Choose-mainmenu → Toolpath → Drill
- Select Entities Choose 10mm diameter circles one by one.
- Choose done. Tool path is generated, Choose once again done
- Right click in the tool display area and select a 10 mm drill mill from the tool library.
- Select the drill parameters and note that the depth should be negative say -60.
- Choose OK twice in the tool path should be showing figure.


Step 5

Tool path Generator

- i. Choose - mainmenu → Operation
- A dialogue box appears select all regenerate path
- When the tool path generation completes the dialogue box display
- choose verify, a deluge box is displayed select run (machine) item.




Operation management of Tool Path



Configuration of Tool path

If your model is square/Rectangle go to shape, select box , suppose your model is Cylindrical go to shape, select cylinder



Step 6

Post processor NC Program

- Choose-mainmenu → Operation
- A dialogue box appears select all regenerate path, choosepost
- Show path (desktop) for saving post processor Notepadfile.

```

%
00000
(PROGRAM NAME - RAGHU123)
(DATE=DD-MM-YY - 30-04-04 TIME=HH:MM - 12:37)
(UNDEFINED TOOL - 1 DIA. OFF. - 41 LEN. - 1 DIA. - 2.5)
N100G21
N102G0G17G40G49G80G90
N104T1M6
N106G0G90G54X-68.75Y38.75A0.S1200M3
N108G43H1260.M8
N110Z5.
N112G120.F2.
N114X88.75
N116Y-38.75

```

Result: The required geometry is created.

Post processor program Exercise 1

```
%  
O0000  
(PROGRAM NAME - 1)  
(DATE=DD-MM-YY - 27-11-07 TIME=HH:MM - 10:05)  
(4. FLAT ENDMILL TOOL - 2 DIA. OFF. - 42 LEN.- 2 DIA. - 4.)  
N100G21 47.R52.N200G1X-22.249 N202G2X-  
N102G0G17G40G49G80G90 47.Y-22.249R52.  
/N104G91G28Z0.  
/N106G28X0.Y0.  
/N108G92X0.Y0.Z0.  
N110T2M6  
N112G0G90X-32.249Y62.A0.S50M5  
N114G43H2Z20.M8  
N116Z5.  
N118G1Z-6.667F2.2  
N120Y57.  
N122G3X-22.249Y47.R10.  
N124G1X22.249  
N126G2X47.Y22.249R52.  
N128G1Y-22.249  
N130G2X22.249Y-  
47.R52.N132G1X-22.249  
N134G2X-47.Y-22.249R52.  
N136G1Y22.249  
N138G2X-22.249Y47.R52.  
N140G3X-  
16.527Y56.038R10.N142X-  
17.489Y60.317R10.  
N144G1X-19.628Y64.836  
N146G0Z10.  
N148X-32.249Y62.  
N150Z5.  
N152G1Z-15.333  
N154Y57.  
N156G3X-22.249Y47.R10.  
N158G1X22.249  
N160G2X47.Y22.249R52.  
N162G1Y-22.249  
N164G2X22.249Y-  
47.R52.N166G1X-22.249  
N168G2X-47.Y-22.249R52.  
N170G1Y22.249  
N172G2X-22.249Y47.R52.  
N174G3X-  
16.527Y56.038R10.N176X-  
17.489Y60.317R10.  
N178G1X-19.628Y64.836  
N180G0Z10.  
N190G3X-22.249Y47.R10.  
N192G1X22.249  
N194G2X47.Y22.249R52.  
N196G1Y-22.249  
N198G2X22.249Y-
```

N204G1Y22.249	47.R52.N268G1X-22.249
N206G2X-	N270G2X-47.Y-22.249R52.
22.249Y47.R52.	N272G1Y22.249
N208G3X-	N274G2X-22.249Y47.R52.
16.527Y56.038R10.	N276G3X-
N210X-	16.527Y56.038R10.N278X-
17.489Y60.317R10.	17.489Y60.317R10.
N212G1X-	N280G1X-19.628Y64.836
19.628Y64.836	N282G0Z10.
N214G0Z10.	N284X-32.249Y62.
N216X-	N286Z5.
32.249Y6	N288G1Z-50.
2.	N290Y57.
N218Z5.	N292G3X-22.249Y47.R10.
N220G	N294G1X22.249
1Z-	N296G2X47.Y22.249R52.
32.667	N298G1Y-22.249
N222Y	
57.	
N224G3X-	
22.249Y47.R10.	
N226G1X22.249	
N228G2X47.Y22.	
249R52.N230G1Y	
-22.249	
N232G2X22.249Y	
-	
47.R52.N234G1X-	
22.249 N236G2X-	
47.Y-22.249R52.	
N238G1Y22.249	
N240G2X-	
22.249Y47.R52.	
N242G3X-	
16.527Y56.038R10.	
N244X-	
17.489Y60.317R10.	
N246G1X-	
19.628Y64.836	
N248G0Z10.	
N250X-	
32.249Y6	
2.	
N252Z5.	
N254G	
1Z-	
41.333	
N256Y	
57.	
N258G3X-	
22.249Y47.R10.	
N260G1X22.249	
N262G2X47.Y22.	
249R52.N264G1Y	
-22.249	
N266G2X22.249Y	
-	

N300G2X22.249Y-47.R52.
N302G1X-22.249
N304G2X-47.Y-22.249R52.
N306G1Y22.249
N308G2X-22.249Y47.R52.
N310G3X-
16.527Y56.038R10.N312X-
17.489Y60.317R10.
N314G1X-19.628Y64.836
N316G0Z20.
N318M5
N320G91G28Z0.M9
N322M01
(6. FLAT ENDMILL TOOL - 1 DIA. OFF. -
41 LEN.- 1 DIA. - 6.)
N324T1M6
N326G0G90X-15.384Y-20.65A0.S50M5
N328G43H1Z20.M8
N330Z5.
N332G1Z-5.333F1.5
N334G2X-25.313Y0.R26.438
N336X-1.125Y24.188R24.188
N338X23.063Y0.R24.188
N340X1.125Y-21.938R21.938
N342X-20.813Y0.R21.938
N344X-1.125Y19.688R19.688
N346X18.563Y0.R19.688
N348X1.125Y-17.438R17.438
N350X-16.313Y0.R17.438
N352X-1.125Y15.188R15.188
N354X14.063Y0.R15.188
N356X1.125Y-12.938R12.938
N358X-11.813Y0.R12.938
N360X-1.125Y10.688R10.688
N362X9.563Y0.R10.688
N364X1.125Y-8.438R8.438
N366X-7.313Y0.R8.438
N368X-1.125Y6.188R6.188
N370X5.063Y0.R6.188
N372X1.125Y-3.938R3.938
N374X-2.813Y0.R3.938
N376X-1.125Y1.688R1.688
N378X.563Y0.R1.688
N380G0Z10.
N382X26.
N384Z5.
N386G1Z-5.333
N388G3X0.Y26.R26.
N390X-
26.Y0.R26.N392X0.
Y-26.R26.
N394X26.Y0.R26.
N396G0Z10.
N398X-15.384Y-20.65

N400Z5.
N402G1Z-12.667
N404G2X-25.313Y0.R26.438

N406X-
 1.125Y24.188R24.188
 N408X23.063Y0.R24.188
 N410X1.125Y-
 21.938R21.938 N412X-
 20.813Y0.R21.938 N414X-
 1.125Y19.688R19.688
 N416X18.563Y0.R19.688
 N418X1.125Y-
 17.438R17.438 N420X-
 16.313Y0.R17.438 N422X-
 1.125Y15.188R15.188
 N424X14.063Y0.R15.188
 N426X1.125Y-
 12.938R12.938 N428X-
 11.813Y0.R12.938 N430X-
 1.125Y10.688R10.688
 N432X9.563Y0.R10.688
 N434X1.125Y-
 8.438R8.438 N436X-
 7.313Y0.R8.438 N438X-
 1.125Y6.188R6.188
 N440X5.063Y0.R6.188
 N442X1.125Y-
 3.938R3.938 N444X-
 2.813Y0.R3.938 N446X-
 1.125Y1.688R1.688
 N448X.563Y0.R1.688
 N450G0Z10.
 N452X26.
 N454Z5.
 N456G1Z-
 12.667
 N458G3X0.Y26.R
 26. N460X-
 26.Y0.R26.N462X
 0.Y-26.R26.
 N464X26.Y0.R26.
 N466G0Z10.
 N468X-15.384Y-
 20.65 N470Z5.
 N472G1Z-20.
 N474G2X-
 25.313Y0.R26.438 N476X-
 1.125Y24.188R24.188
 N478X23.063Y0.R24.188
 N480X1.125Y-
 21.938R21.938 N482X-
 20.813Y0.R21.938 N484X-
 1.125Y19.688R19.688
 N486X18.563Y0.R19.688
 N488X1.125Y-
 17.438R17.438 N490X-
 16.313Y0.R17.438 N492X-
 1.125Y15.188R15.188
 N494X14.063Y0.R15.188
 N496X1.125Y-12.938R12.938
 N498X-11.813Y0.R12.938
 N500X-1.125Y10.688R10.688
 N502X9.563Y0.R10.688
 N504X1.125Y-8.438R8.438
 N506X-7.313Y0.R8.438
 N508X-1.125Y6.188R6.188
 N510X5.063Y0.R6.188
 N512X1.125Y-3.938R3.938
 N514X-2.813Y0.R3.938


N516X-1.125Y1.688R1.688
N518X.563Y0.R1.688
N520G0Z10.
N522X26.
N524Z5.
N526G1Z-20.
N528G3X0.Y26.R26.
N530X-
26.Y0.R26.N532X0.
Y-26.R26.
N534X26.Y0.R26.
N536G0Z10.
N538Z20.
N540X-6.047Y9.487
N542Z5.
N544G1Z-6.
N546G2X-1.125Y10.688R10.688
N548X9.563Y0.R10.688
N550X1.125Y-8.438R8.438
N552X-7.313Y0.R8.438
N554X-1.125Y6.188R6.188
N556X5.063Y0.R6.188
N558X1.125Y-3.938R3.938
N560X-2.813Y0.R3.938
N562X-1.125Y1.688R1.688
N564X.563Y0.R1.688
N566G0Z10.
N568X11.5
N570Z5.
N572G1Z-
6.N574G3X0.Y11.5R11
.5 N576X-
11.5Y0.R11.5
N578X0.Y-11.5R11.5
N580X11.5Y0.R11.5
N582G0Z10.
N584X-6.047Y9.487
N586Z5.
N588G1Z-14.
N590G2X-1.125Y10.688R10.688
N592X9.563Y0.R10.688
N594X1.125Y-8.438R8.438
N596X-7.313Y0.R8.438
N598X-1.125Y6.188R6.188
N600X5.063Y0.R6.188
N602X1.125Y-3.938R3.938
N604X-2.813Y0.R3.938
N606X-1.125Y1.688R1.688
N608X.563Y0.R1.688
N610G0Z10.
N612X11.5
N614Z5.
N616G1Z-14.
N618G3X0.Y11.5R11.5

N620X-11.5Y0.R11.5 N622X0.Y-
11.5R11.5 N624X11.5Y0.R11.5

N626G0Z10.	1.125Y10.688R10.688
N628X	N680X9.563Y0.R10.688
-	N682X1.125Y-8.438R8.438
6.047Y	N684X-7.313Y0.R8.438
9.487	N686X-1.125Y6.188R6.188
N630Z	N688X5.063Y0.R6.188
5.	N690X1.125Y-3.938R3.938
N632G1Z-22.	N692X-2.813Y0.R3.938
N634G2X-	N694X-1.125Y1.688R1.688
1.125Y10.688R10.6	N696X.563Y0.R1.688
88	N698G0Z10.
N636X9.563Y0.R1	N700X11.5
0.688	N702Z5.
N638X1.125Y-	N704G1Z-
8.438R8.438	30.N706G3X0.Y11.5R1
N640X-	1.5 N708X-
7.313Y0.R8.438	11.5Y0.R11.5
N642X-	N710X0.Y-11.5R11.5
1.125Y6.188R	N712X11.5Y0.R11.5
6.188	N714G0Z10.
N644X5.063	N716Z20.
Y0.R6.188	N718G98G81X28.284Y28.284Z-50.R5.F1.5
N646X1.125	N720X-28.284
Y-	N722Y-28.284
3.938R3.938	N724X28.284
N648X-	N726G80
2.813Y0.R3.9	N728M5
38 N650X-	N730G91G0G28Z0.M9
1.125Y1.688R	N732G90
1.688	N734M30
N652X.563Y	
0.R1.688	
N654G0Z10.6	
56X11.5	
N658Z5.	
N660G1-	
22.N662G	
3X0.Y11.	
5R11.5	
N664X-	
11.5Y0.R	
11.5	
N666X0.	
Y11.5R1.	
5	
N668X11.	
5Y0.R115	
N670G0Z	
10.	
N672X	
-	
6.047Y	
9.487	
N6745.	
N676G1Z-30.	
N678G2X-	

Exercise 2

Aim : To machine the model as per the sketch.



Procedure:

Step 1

The usual modification is that is done after initializing the master cam is the alteration of the available screen ie modification of grid size and as per the requirement of user screen,

Choose-mainmenu → Screen → Configure → Current Configuration File

Select- Mill9.Mcfg(metric)

Choose-mainmenu → Screen → Nextmenu → Sel.Grid

Select-Active Grid, Visible Grid, Spacing x =1 and y =1, Grid Size= 110,

Origin x=0,y=0 and choose suitable for Grid.

Step 2

1. To create inner and outercircles.
 - Choose-mainmenu → Create → Arc → circpt +dia.
 - Typediameter100 → Enter
 - Selectorigin
 - Press Esc. And reselectcircpt+dia
 - Enter diameter85
 - Selectorigin
 - Press Esc. And reselectcircpt+dia
 - Repeat same procedure for diameter 93mm
 - Selectorigin
 - Press Esc. to exit circle function Press Esc. And reselectcircpt+dia
 - Repeat same procedure for pitch circle diameter 3mm
 - Selectquadrant
 - Press Esc. to exit circlefunction
 - Choose it screenmenu.

2. Copy and rotate the 3 mmcircle
 - Choose-mainmenu → Xform → Rotate
 - Select anywhere on 3mmcircle
 - Choosedone.
 - Selectorigin.
 - Select copy, enter the values. No of steps 11 and angle is30⁰
 - Choose OK in the dialogue box remaining slots forcreated.

3. To create construction of rectangle /Square
 - Choose-mainmenu → Create → Rectangle → 1 point
 - Enter width 150 and height 150 (bcz. given figure is square) pressOK
 - Selectorigin,
 - Press Esc.
 - Enter width 140 and height 140 (bcz. given figure is square) pressOK
 - Selectorigin
 - Press Esc to exit Rectangle function.

4. To create construction offlines

- Choose-mainmenu → Create → Line → Endpoint
- Enter the first co-ordinate Midpoint of horizontal line of 140mmSquare
- Enter the Second co-ordinate Midpoint of Vertical line of 140mmSquare
- Enter the same method for other threesides
- Press Esc to exit linefunction

5. To create construction offline

- Choose-mainmenu → Create → Line → Polar
- Enter the first co-ordinateorigin
- Enter angle in degree45⁰
- Enter the line length70
- Press Esc to exit linefunction

6. To create inner 10 mm and 15 mm diametercircles

- Choose-mainmenu → Create → Arc → circpt+dia.
- Typediameter10 → Enter
- Select end point of inclinedline.
- Press Esc. And reselectcircpt+dia
- Choose-mainmenu → Xform → Offset
- Choose operation = copy, No. of steps =1 & Offset distance= 2.5mm
- Select 10 mm diacircle
- Click outside the circle (Direction Inside or Outside)
- ThenoK

7. Copy and rotate theCircle

- Choose-mainmenu → Xform → Rotate
- Select anywhere on 10 & 15 mm diametercircle
- Choose done. Selectorigin.
- Select copy, enter the values. No of steps 3 and angle is90⁰
- Choose OK in the dialogue box remaining 3 circles forcreated.

Now your drawing is ready for operations

The following operations to be conduct Using the geometry

Facing, Contours, Pocketing and Drilling

Step 3

1. Make job setup for givengeometry

- Choose-mainmenu → Toolpath → Jobsetup
- Enter the X =155 Y=155 and Z=65 mmrespectively
- Select Display Stack and Fit toScreen.
- Out side the drawing doted boundary red line isdisplayed

2. Another option for jobsetup

- Choose-mainmenu → Toolpath → Job setup
- Select stock origin (0,0)
- select the stockcorners.
- Enter the value of Z = 65 (+ value).
- Select the display stock checkbox.
- Select fit stock checkbox.
- Choose OK the stock should be enclosed by red dottedline.

Step 4

1. Create tool path forFacing

- Choose-mainmenu → Toolpath → Face
- Select start point for the chain at periphery of thefigure.
- Choosedone.
- Right click in the tool display area and select a 10 mm flat endmill
- from the toollibrary.
- Right click on the tool display , go to tool type select face milltool,
- Select the facing parameters. Give Depth of cut -3mm (-negative)
- Select depth Cuts, Give Rough Cut 3, Finishing cut 1No. Finish Step0.5
- Choose OK twice in the tool path should be showingfigure.

2. Create tool path for Contour 1,2 &3

- Choose-mainmenu → Toolpath → Contour
- Select 100mm diameter circle.
- Choosedone.
- Right click in the tool display area and select a 12 mm flat end mill from the tool library.
- Select the contour parameters, Give Depth of cut -3mm - negative, (Cumulative ie 3+3=6mm)
- Use Multi passes and Depth Cuts options.
- Choose OK twice in the tool path should be showing figure.
- Repeat same procedure for other contours for
- Rambo's Square with depth 3 mm, (Cumulative ie 3+3+3=9mm)
- Filleted Square with depth 3 mm, (Cumulative ie 3+3+3+3=12mm)

Create tool path for Contour4

- Choose-mainmenu → Toolpath → Contour
- Select start point for the chain at position 1. (outer periphery of the square)
- Choosedone.
- Right click in the tool display area and select a 5 mm flat end mill from the tool library.
- Select the contour parameters, Give Depth of cut -65mm (- negative), Use Multi passes, Depth Cuts and Lead in/out options.
- Choose OK twice in the tool path should be showing figure.

3. Create tool path for pocket1

- Choose-mainmenu → Toolpath → Pocket
- Select the 86 mm diameter circle.
- Choosedone.
- Right click in tool display area and select 8mm flat end mill from tool library.
- Enter pocketing parameters and note that the depth should be negative say -65.

- Choose OK the tool path should look like the picture pattern. 4
- Create tool path for pocket2

- Choose-mainmenu → Toolpath → Pocket
- Select first 15 mm diameter circle.
- Choose done.
- Right click in tool display area and select 3mm flat end mill from tool library.
- Enter pocketing parameters and note that the depth should be negative say -15.
- Choose OK the tool path should look like the picture pattern.

5. Create tool path for Drilling 1 (10 mm dia)

- Choose-mainmenu → Toolpath → Drill
- Select Entities Choose 10mm diameter circles one by one.
- Choose done. Tool path is generated, Choose once again done
- Right click in the tool display area and select a 10 mm drill mill from the tool library.
- Select the drill parameters and note that the depth should be negative -68.
- Choose-Esc

Create tool path for Drilling 2 (03 mm dia)


- Toolpath Drill
- Select Entities Choose 3 mm diameter circles one by one.
- Choose done. Tool path is generated, Choose once again done
- Right click in the tool display area and select a 3 mm drill mill from the tool library.
- Select the drill parameters and note that the depth should be negative -30.
- Choose OK twice in the tool path should be showing figure

Step 5


Tool path Generator

- Choose-mainmenu → Operation
- A dialogue box appears select all , regenerate path
- When the tool path generation completes the dialogue box display
- choose verify,

- Verify true solid deluge box is displayed select run (machine) item.
- Verify true solid deluge box go to Configure
 Select Job Box or Cylinder,
 Select use job setup values for present file operations
 In Display control, use Simulation speed / quality variations
 In miscellaneous select use true solid & Cutter compensation in control In Toll
 select Solid tool.




Operation management of Tool Path



Configuration of Tool path

If your model is square/Rectangle go to shape, select box , suppose your model is Cylindrical go to shape, select cylinder



Step 6

Post processor NC Program

- Choose-mainmenu → Operation
- A dialogue box appears select all regenerate path, choosepost
- Show path (desktop) for saving post processor Notepadfile.




```
Programmer's File Editor
File Edit Options Template Execute Macro Window Help
raghu123.nc
%
00000
(PROGRAM NAME - RAGHU123)
( DATE=DD-MM-YY - 30-04-04 TIME=HH:MM - 12:37)
( UNDEFINED TOOL - 1 DIA. OFF. - 41 LEN. - 1 DIA. - 2.5)
N100G21
N102G0G17G40G49G80G90
N104T1M6
N106G0G90G54X-68.75Y38.75A0.S1200M3
N108G43H1260.M8
N110Z5.
N112G120.F2.
N114X88.75
N116Y-38.75
Ln 1 Col 1 23 WR Rec Off No Wrap DOS INS NUM
```

Exercise No.3

SPROCKET

Aim : To machine the model as per thesketch.



Procedure:

Step 1

The usual modification is that is done after initializing the master cam is the alteration of the available screen ie modification of grid size and as per the requirement of user screen,

Choose-mainmenu → Screen → Configure → Current Configuration File

Select- Mill9.Mcfg(metric)

Choose-mainmenu → Screen → Nextmenu → Sel. Grid

Select-Active Grid, Visible Grid, Spacing x =1 and y =1, Grid Size= 200, Origin x=0,y=0 and choose suitable for Grid.

Step 2

To create inner and outer circles.

- Choose-mainmenu → Create → Arc → circpt +dia.

- Typediameter188 → Enter
- Selectorigin
- Press Esc. And reselectcircpt+dia
- Enter diameter174
- Selectorigin
- Press Esc. And reselectcircpt+dia
- Repeat same procedure for pitch circle diameter 12mm
- Selectquadrant
- Press Esc. to exit circlefunction
- Choose it screenmenu.
- Create arc 3points
- First point – intersection of 12mm & 188 mm diacircles.
- Second point – quadrant of 174 mmcircle
- Third point is again opposite side of First point – intersection of 12mm & 188 mm diacircles.
- Delete 12 mmcircle

Copy and rotate the 3 point arc

- Choose-mainmenu → Xform → Rotate
- Select anywhere on 3 pointarc
- Choosedone.
- Selectorigin.
- Select copy, enter the values. No of steps 44 and angle is $360/45^0$
- Choose OK in the dialogue box remaining arcs forcreated.

Trimming unwanted portion of teeth

- Choose-mainmenu → Modify → Trim → 3entities
- Select 1 Entity Select 3 point arc inside the 188 mm dia circle 2 Entity adjacent 3 point arc inside the 188 mm diacircle 3 Entity 188 mm dia circle in between the two 3point arcs.

Copy and rotate the 188 mm dia circle in between the two 3point arcs

- Choose-mainmenu → Xform → Rotate

- Select anywhere on arc in between the two 3pointarcs
- Choosedone.
- Selectorigin.
- Select copy, enter the values. No of steps 44 and angle is $360/45^0$
- Choose OK in the dialogue box remaining arcs forcreated.
- Choose-mainmenu → Create Arc → circpt → dia.
- Typediameter140 → Enter
- Selectorigin
- Repeat same procedure for diameter 70mm
- Selectorigin

To create construction offline

- Choose-mainmenu → Create → Line → multiline
- Enter the first point isorigin
- Enter the Second point is quadrant of 140 mm diacircle.
- Press Esc to exit linefunction
- Go to xform offset select the line offset distance10mm
- Repeat the same by 15mm
- Choose-mainmenu → Create → Line → multiline
- Enter the first point is intersection of 140mmcircle and 10 mm offsetline
- Enter the Second point is intersection of 70 mm circle and 15 mm offset line.
- Delete both offsetlines
- Go to fillet select radius 10mm
- Enter the first inclinedline
- Enter the Second 140mm diacircle.
- Same steps repeat for 70mm diacircle

To create construction of line

- Choose-mainmenu → Create → Line → Polar
- Enter the first co-ordinateorigin
- Enter angle in degree 45^0
- Enter the line length 145

Trimming unwanted portion of 140/70 dia circle

- Choose-mainmenu → Modify → Trim → 3 entities
- Select
 - 1 Entity Select 140 mm diacircle
 - 2 Entity Select 70 mm diacircle
 - 3 Entity 45⁰ line in between 140 and 70 diacircles.

Mirror

- Choose-mainmenu → Xform → Mirror
- Select chain, anywhere on fillet/line/arc
- End here, done, Mirror about line
- Choosedone.

Copy and rotate the mirrored item

- Choose-mainmenu → Xform → Rotate
- Select chain, End here,
- Choosedone.
- Select origin.
- Select copy, enter the values. No of steps 3 and angle is 90⁰
- Choose OK in the dialogue box remaining arcs for created.

To create inner 55 mm and 95 mm diameter circles

- Choose-mainmenu → Create → Arc → circpt+dia.
- Type diameter 55 → Enter
- Go to backup,
- circpt + dia 95mm
- Press Esc., and reselect circpt+dia
- Then OK

To create inner 08mm diameter circles

- Choose-mainmenu → Create → Line → Polar
- Enter the first co-ordinate origin
- Enter angle in degree 0⁰
- Enter the line length 40

- Press esc to exit line function
- Choose-mainmenu → Create → Arc → circpt +dia 8mm enter
End point go and Select of theline

Copy and rotate the Circle

- Choose-mainmenu → Xform → Rotate
- Select anywhere on 8 mm diametercircle
- Choose done. Selectorigin.
- Select copy, enter the values. No of steps 3 and angle is90⁰
- Choose OK in the dialogue box remaining 3 circles forcreated.

Now your drawing is ready for operations

The following operations to be conduct using the geometry

Facing, Contours, Pocketing and Drilling

Step 3

1. Make job setup for givengeometry

- Choose-mainmenu → Toolpath → Jobsetup
- Enter the X =190 Y=190 and Z= 11 mmrespectively
- Select Display Stack and Fit toScreen.
- Out side the drawing doted boundary red line isdisplayed

2. Another option for jobsetup

- Choose-mainmenu → Toolpath → Job setup
- Select stock origin (0,0)
- Select the stock corners.
- Enter the value of Z = 11 (+ value).
- Select the display stock checkbox.
- Select fit stock checkbox.
- Choose OK the stock should be enclosed by red dottedline.

Step 4

Create tool path for Facing

- Choose-mainmenu → Toolpath → Face
- Select start point for the chain at periphery (Teeth) of the figure.
- Chooedone.
- Right click in the tool display area and select a 10 mm flat end mill from the tool library.
- Right click on the tool display , go to tool type select face mill tool,
- Select the facing parameters. Give Depth of cut -3mm (-negative)
- Select depth Cuts, Give Rough Cut 2, Finishing cut 1 No. Finish Step 1
- Choose OK twice in the tool path should be showing figure.

Create tool path for Contour

- Choose-mainmenu → Toolpath → Contour
- Select start point for the chain at periphery (Teeth) of the figure.
- Chooedone.
- Right click in the tool display area and select a 3 mm flat end mill from the tool library.
- Select the contour parameters , Give Depth of cut -8 mm - negative, (Cumulative ie $3+8=11$ mm)
- Use 3 Multi passes with spacing 2 mm and Depth Cuts options. Select depth Cuts, Give Rough Cut 3, Finishing cut 2 No. Finish Step 1
- Choose OK twice in the tool path should be showing figure.

Create tool path for pocket 1,2,3,4 and 5


- Choose-mainmenu → Toolpath → Pocket
- Select the 55 mm diameter circle, another 4 slots packet.
- Chooedone.
- Right click in tool display area and select 5 mm flat end mill from tool library.
- Enter pocketing parameters and note that the depth should be negative say -8.
- Choose OK the tool path should look like the picture pattern.

Create tool path for pocket 95 mm dia

- Choose-mainmenu → Toolpath → Pocket
- Select first 95 mm diameter circle.
- Choosedone.
- Right click in tool display area and select 10mm flat end mill from toollibrary.
- Enter pocketing parameters and note that the depth should be negative say -6.
- Choose OK the tool path should look like the picture pattern.

Create tool path for Drilling 1 (08 mm dia)


- Choose-mainmenu → Tool path → Drill
- Select Entities Choose 8 mm diameter 4 circles one by one.
- Choose done. Tool path is generated, Choose once again done
- Right click in the tool display area and select a 8 mm drill mill from the tool library.
- Select the drill parameters and note that the depth should be negative -10.
- Choose-Esc



Exercise No. 4

Gear

Aim : To machine the model as per the sketch.



Procedure:

Step 1

The usual modification is that is done after initializing the master cam is the alteration of the available screen ie modification of grid size and as per the requirement of user screen,

Choose-mainmenu → Screen → Configure → Current Configuration File

Select- Mill9.Mcfg(metric)

Choose-mainmenu → Screen → Nextmenu → Sel. Grid

Select-Active Grid, Visible Grid, Spacing x =1 and y =1, Grid Size= 100,

Origin x=0,y=0 and choose suitable for Grid.

Step 2

To create inner and outer circles.

- → Choose-mainmenu → Create Arc circpt +dia.

- Typediameter 72 →Enter
- Selectorigin
- Press Esc. And reselectcircpt+dia
- Go tobackup
- And reselectcircpt+dia
- Enter diameter56
- Selectorigin
- Press Esc. And reselectcircpt+dia
- Then create one pitch enter circle for diameter 64mm
- Selectorigin
- Press Esc. And reselectcircpt+dia
- Repeat same procedure for pitch circle diameter 7mm
- Select quadrant of 25 mmdia
- Press Esc. to exit circlefunction


To create construction offline

- Choose-mainmenu → Create → Line → multiline
- Enter the first point isorigin
- Enter the Second point is quadrant of 72 mm diacircle.
- Press Esc to exit linefunction
- Go to xform offset select the line offset distance 1.5mm
- Repeat the same by 3.0mm
- Again go to xform offset select the line offset distance 0.75 mm (inbetween line 1.5 – 3)

Choose, menu, create, Arc

- Create arc 3points

1




- First point – intersection of 72mm circle & offset line3mm.
- Second point – intersection of 64mm circle & 1.5 +0.75 mm offset line.
- Third point - intersection of 56 mm circle & offset line3mm.

Same procedure is repeat opposite side

Delete all the vertical line and 64 mm diameter circle

Trimming unwanted portion of teeth

- Choose-mainmenu → Modify → Trim → 2entities
- Select 1 Entity Select 3 point arc (No.3) inside the 56 mm diacircle
 2 Entity adjacent 3 pointarc(No.1) inside the 72 mm diacircle



Fillet

- Choose-mainmenu → Create → Fillet
- Radius, take 0.5 mm,enter
- Select item 1 arc and dia 72circle
- Repeat the procedure item 3arc and dia 56circle

Mirror

- Choose-mainmenu → Xform → Mirror
- Select four 4 entities one by one 1) fillet, 2) item No 3 arc, 3) item No 1 arc and 4)fillet
- End here, done , Mirror about line or yaxis
- Choosedone.

Trimming unwanted portion of teeth

- Choose-mainmenu → Modify → Trim → 2 entities
Select 1 Entity Select fillet of theteeth
2 Entity Select 72 mm dia circle inside portion of teeth

Copy and rotate the gear teeth

- Choose-mainmenu → Xform → Rotate
- Select gearteeth
- Choosedone.
- Selectorigin.
- Select copy, enter the values. No of steps 15 and angle is $360^{\circ}/16$
- Choose OK in the dialogue box remainingteeths.

Trimming unwanted portion of teeth

- Choose-mainmenu → Modify → Trim → 3 entities
Select 1 Entity Select fillet of the teeth (dia56)
 2 Entity Select opposite fillet of the teeth (dia56)
 3 Entity Select 56 mm dia circle in between twofillet

Copy and rotate the dedandam arc ie 56 dia circle

- Choose-mainmenu → Xform → Rotate
- Select 56 mm dia circle in between twofillet
- Choosedone.
- Selectorigin.
- Select copy, enter the values. No of steps 15 and angle is $360^{\circ}/16$
- Choose OK in the dialogue box remainingteeths.

Now your drawing is ready for operations

The following operations to be conduct using the geometry

Facing, Contours, Pocketing and Drilling

Step 3

1. Make job setup for givengeometry

- Choose-mainmenu → Toolpath → Jobsetup
- Enter the X =75 Y= 75 and Z= 33 mmrespectively
- Select Display Stack and Fit toScreen.
- Out side the drawing doted boundary red line isdisplayed

Step 4

Create tool path for Facing

- Choose-mainmenu → Toolpath → Face
- Select start point for the chain at periphery (Teeth) of the figure.
- Chooedone.
- Right click in the tool display area and select a 10 mm flat end mill from the toollibrary.
- Right click on the tool display , go to tool type select face milltool,
- Select the facing parameters. Give Depth of cut -3mm (-negative)
- Select depth Cuts, Give Rough Cut 2, Finishing cut 1 No. Finish Step1
- Choose OK twice in the tool path should be showingfigure.

Create tool path for Contour


- Choose-mainmenu → Toolpath → Contour
- Select start point for the chain at periphery (Teeth) of the figure.
- Chooedone.
- Right click in the tool display area and select a 2 mm flat end mill from the toollibrary.
- Select the contour parameters , Give Depth of cut -33 mm - negative, (Cumulative ie $3 + 30 = 33\text{mm}$)
- Use 5 Multi passes with spacing 1 mm and Depth Cuts options. Select depth Cuts, Give Rough Cut 4, Finishing cut 3 No. Finish Step2
- Choose OK twice in the tool path should be showingfigure.

Create tool path for pocket

- Choose-mainmenu → Toolpath → Pocket
- Select the 25 mm diameter circle,
- Chooedone.
- Right click in tool display area and select 5 mm flat end mill from toollibrary.
- Enter pocketing parameters and note that the depth shouldbe negative say-33.
- Choose OK the tool path should look like the picturepattern.

Create tool path for Drilling 1 (07 mm dia)



- Choose-mainmenu → Toolpath → Drill
- Select Entities Choose 8 mmdiameter.
- Choose done. Tool path is generated, Choose once again done
- Right click in the tool display area and select a 7 mm drill mill from the tool library.
- Select the drill parameters and note that the depth should be negative -35.
- Choose-Esc



Exercise 5

CAM


Aim : To machine the model as per the sketch.




Exercise No. 6

Plate

Aim : To machine the model as per the sketch.





Exercise No. 7

Gear

